

BL15

B-LINE is a range of safety eyewear **accessible to all** and is adapted to the most common industrial risks. **B-LINE** benefits from Bollé Safety's expertise and quality.

Simple and economic, BL15 goggles fit to all and can be worn over glasses.

B LINE



BL15API
(Vented)



BL15APSI
(Vented)



PSGBL15-A02
(Sealed)



Vented versions

Sealed version












77 g

- + **CLEAR TRANSLUCENT FRAME**
- + **SEALED OR VENTED VERSIONS**
- + **AVAILABLE WITH ANTI-FOG & ASAF COATINGS**
- + **ADJUSTABLE STRAP**
- + **FITS OVER PRESCRIPTION GLASSES**

bollé
SAFETY

BL15

MODEL	VERSIONS	REFERENCES	LENS MARKINGS	FRAME MARKINGS	COATINGS
BL15	 Clear Vented	BL15API	 1 9 BT CE	 EN166 3 4 9 BT CE	-
	 Clear Vented	BL15APSI	 1 BT CE	 EN166 3 4 9 BT CE	AF
	 Clear Sealed	PSGBL15-A02	 1 BT CE	 EN166 3 4 5 BT CE	ASAF

LENS MARKINGS

Optical class symbols:

1. Continuous work

Use symbols:


9. Molten metal and hot solids.

Mechanical strength symbols:

B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s.

T. The letter T, immediately after the mechanical strength symbol, authorises use for high speed particles at extreme temperatures.

Others symbols:

CE European standard  Manufacturer name

FRAME MARKINGS

EN 166: guaranteed minimum resistance of the protective eyewear against everyday risks including dropping the protective eyewear onto the ground, ageing by light exposure, exposure to heat or corrosion etc.

3. Liquid droplets.

4. Large dust particles > 5 microns.

5. Gas and fine dust particles < 5 microns.

9. Molten metal and hot solids.

B. Medium energy impact, resists a 6 mm, 0.86 g ball at 120 m/s.

T. The letter T, immediately after the mechanical strength symbol, authorises use for high speed particles at extreme temperatures.

Others symbols:

CE European standard  Manufacturer name

Bollé Safety product approval certificates to standards will be sent on request.

CLEANING AND STORAGE

CLEANING: The lenses should be cleaned regularly. Bollé Safety recommends only using the B-clean lens cleaning system.

MAINTENANCE: Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: All products must be stored in a dry and clean environment.

PACKAGING AND EAN13 CODE

	BL15API	BL15APSI	PSGBL15-A02
Individual plastic bag	3660740003036	3660740003043	3660740010430
180 safety goggles per outer pack	3660740203030	3660740203047	3660740200435

CARACTERISTICS

LENS	PC - 2 mm - Curve 4
FRAME	PVC
STRAP	Polyester
SPARE LENS	No



13/03/2020

Europe Bollé Safety
34 rue de la Soie
69100 Villeurbanne - France
Tél. : 00 33 (0) 4 78 85 23 64
Fax : 00 33 (0) 4 78 85 28 56
contact@bolle-safety.com

bolle-safety.com

U.K. Bollé Safety
Unit C83 - Barwell Business Park Leatherhead Road - Chessington
Surrey - KT9 2NY - UK
Tél. : 00 44 (0)208 391 4700
Fax : 00 44 (0)208 391 4733
e-mail : sales@bolle-safety.co.uk

bolle
SAFETY