

ULTIM8

THE ULTIMATE RESISTANCE

The most advanced protection for extreme work environments (cold/hot/dust/humid environments/oil & gas industries, mining...). ULTIM8 offers maximum resistance to fogging thanks to PLATINUM® coating.

 PLATINUM®



ULTIPSI

SUPPLIED WITH



Goggle Conversion
Kit Retainer Strap



64 g

SUPPLIED WITH

Transformation kit:
removable temples



Worn as spectacles with
temples kit



Worn as spectacles with
retainer strap (provided)



Pivoting temples

- + PIVOTING PC/TPR TEMPLES**
- + WATERPROOF TPR FOAM**
- + ADJUSTABLE AND REMOVABLE STRAP**
- + TEMPLE/GOGGLES TRANSFORMATION KIT**
- +  PLATINUM (+P) COATING**

bolle
SAFETY

ULTIM8

THE ULTIMATE RESISTANCE

MODEL	VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
ULTIM8	 Clear	ULTIPSI	IO	AS/NZS 1337.1.2010	Anti-scratch/Anti-fog/ 

LENS MARKING

 Platinum is a permanent coating applied on both sides of the lens that gives a high resistance to scratching ($1.4 \text{ cd} / \text{m}^2$) and to the most aggressive chemicals and delays the onset of fogging for two minutes, as per the testing requirements of EN166.

- I. The letter 'I' signifies 'Medium Impact' approval.
- O. The letter 'O' signifies that the product has been approved for the use both outdoors and indoors, and the terminology used by Australian standards is 'outdoor un-tinted'. This marking appears on all clear, amber and contrast lenses.

Ocular lens category:

- O. Range of luminous transmittance 80–100% (Clear).

TECHNOLOGIES

PLATINUM

The new exclusive scratch and fog resistant coating K and N certified PLATINUM® guarantees even more safety, reliability and comfort. Washable (water and soap), this permanent coating applied on both sides of the lens makes it highly scratch-resistant and effectively delays the appearance of fogging.

LENSES

- 2mm polycarbonate
- Platinum coating on both sides of Clear
- 100% UV 385 – Clear

FRAME MARKING

AS/NZS 1337.1.2010: Tested and approved to AS/NZS 1337.1.2010 – Medium Impact protection. Meets the requirement of splash approval when used with the supplied head strap correctly adjusted.

CLEANING AND STORAGE

CLEANING: The lenses should be cleaned regularly. Bollé Safety recommends only using the B-clean lens cleaning system.

MAINTENANCE: Pitted, scratched or damaged lenses must be replaced by replacing the complete product. If the frame is damaged also replace the complete product. After each use it is recommended to keep the spectacles or goggles in a microfiber pouch or rigid case.

STORAGE: All products must be stored in a dry and clean environment.

CHARACTERISTICS	
LENSES	PC – 2,2 mm – Curve 8
STRAP	15mm adjustable – Polyester
FOAM	TPR

22/05/2018

ASIA/PACIFIC HEADQUARTERS:

Bollé Australia Pty Ltd
32–40 Fairchild Street
Heatherton VIC 3202
T: 1300 138 098
E: safety@bolle.com.au

bollesafety.com.au

NEW ZEALAND:

T.: 0800 2655 369
E: bolle@bolle.co.nz

bolle
SAFETY