

CHRONOSOFT

ULTIMATE PROTECTION

Ideal for high heat environments, CHRONOSOFT goggles are an example of high-end innovation. The elastomer frame withstands extreme heat. The double lens features the EQUALIZER® system for highly effective fog protection.



CHRONOSOFT ADVANTAGES

- ▶ EQUALIZER TECHNOLOGY
- ▶ KRATON™ FRAME
- ▶ RATED D3 / D4 / D5 / LIQUID SPLASH / DUST / FINE DUST
- ▶ LATEX FREE ADJUSTABLE STRAP
- ▶ RX PRESCRIPTION INSERT AVAILABLE

bolle
SAFETY

CHRONOSOFT

TAKE THE HEAT SEE CLEARLY

Ideal for high heat environments, CHRONOSOFT goggles are an example of high-end innovation. The elastomer frame withstands extreme heat. The double lens features the EQUALIZER® system for highly effective fog protection.

99.99% UVA and UVB light absorption



Equalizer technology removes moisture from between the front and back lenses while balancing the inner goggle temperature and pressure with the outside environment to eliminate lens fogging

High impact double polycarbonate lens, anti-fog/anti-scratch coated

Excellent peripheral vision

High impact 2.2 mm polycarbonate lens, anti-fog/anti-scratch coated

4.4 OZ

RATED

D3 Liquid Splash Protection

D4 Dust Protection




D5 Fine Dust Protection

SPECIFICATIONS

CHARACTERISTICS

Lens Material: Polycarbonate
Lens Thickness: 2.2 mm & 1.1mm
Frame Material: KRATON™
Base Curve: 6



VERSIONS	REFERENCES	LENS MARKING	FRAME MARKING	COATINGS
 Clear	40102	 Z87+U6	 Z87+D3,D4,D5/Z94	Anti-scratch/Anti-fog
Rx Insert	40103	N/A	N/A	N/A
Strap + Retainer	40165	N/A	N/A	N/A

UNIT	40102	40103	40165
INDIVIDUAL	0-54917-27794-9	0-54917-27795-6	0-54917-28665-1
INNER PACK	10	30	50
MASTER PACK	160	300	600

OPTIONAL RX INSERT
AVAILABLE (40103)



CLEANING

Lenses should be cleaned regularly. Bollé Safety recommends using the B-clean lens cleaning system.

STORAGE

Must be stored in a clean, dry environment. After each use, keep product in a microfiber pouch or rigid case.

REPLACEMENT

If lenses or frames are pitted, scratched or damaged, the complete product must be replaced.